


3-Right now, the over hang towards the left is about 8 inches. If this is a problem, we could put in a blind corner cabinet instead of the lazy susan corner cabinet that is currently in there. This line on the wall, this is the end of the measurement that I got from the installers.



All dimensions _size designations given are subject to verification on job site and adjustment to fit job conditions.

This is an original design and must not be released or copied unless applicable fee has been paid or job order placed.

Designed: 5/10/2023 Printed: 5/10/2023